
ANCHOR MC
Wave Direction
ANCHOR MK
MC Mooring line
MK Mooring Line
Load cell bad
At deployment
Load cell bad
After 46 hours
Load cell MC
Load cell MK
Load cell AB-C
Load cell AB-K
These Load Cells are good
AB Bridal
AB Mooring Line
ANCHOR AB